□ No

Status Date: 02/28/2023 09:27 PM - Submitted

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Information
Page Last Modified: 02/28/2023
Building Information
1. Name of school district
Rye Neck Union Free School District
2. SED District 8-Digit BEDS Code
66-19-01-03
3. Building Name:
Rye Neck Middle School-High School Gymnasium
4. SED 4-Digit Facility Code:
0001
5. Survey Inspection Date: 07/26/2022
6. Building 911 Address:
300 Hornidge Road
7. City:
Mamaroneck
8. Zip Code:
10543
9. Certificate of Occupancy Status:
. ✓ A - Annual
□ T - Temporary
□ N - None
10. Certificate of Occupancy Expiration Date: 01/01/2024
10a. Is this a manufactured building? (Relocatable, modular, portable)
□ Yes
✓ No
11. Have there been renovations or construction in the building during the past 12 months?
✓ Yes
□ No
12. Was major construction/renovation work since 2015 conducted when school was in session?
✓ Yes

Page 1 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Information

Page Last Modified: 02/28/2023

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete) 500,000.00 14. Overall building rating (to be answered after the building inspection is complete) □ Excellent ☑ Satisfactory □ Unsatisfactory □ Failing 15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)? ✓ Yes □ No 16. A/E Firm Name: LAN Associates, EPAS, LLP 17. A/E Firm Address: 252 Main Street, Goshen, NY 10924 18. A/E Firm Phone Number: 8456150350 19. E-mail: danielle.farrell@lanassociates.com 20. A/E Name: Danielle L. Farrell, AIA

Building Age, Gross Square Footage and Maintenance Staff

22. Building Age

21. A/E License #:

039812

	Year	
Original Construction	1972	
Addition #1	2021	
Addition #2	(No Response)	
Addition #3	(No Response)	
Addition #4	(No Response)	
Addition #5	(No Response)	
Addition #6	(No Response)	

06/05/2023 10:50 AM Page 2 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Information

Page Last Modified: 02/28/2023

	Year
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

23. Square feet of construction

0.0444.0.000.0.0000.0000.00000.00000000			
	Sq Feet		
Original construction	30,390.00		
Addition #1	36,268.00		
Addition #2	(No Response)		
Addition #3	(No Response)		
Addition #4	(No Response)		
Addition #5	(No Response)		
Addition #6	(No Response)		
Addition #7	(No Response)		
Addition #8	(No Response)		
Addition #9	(No Response)		

24. Gross square ft. of Building as currently configured:

66,658

25. Number of Floors:

1

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	0
Part-time custodians:	0
Totals:	0

Building Ownership and Occupancy Status

27. Building Ownership (check one):

- Owned and used by district
- □ Owned by District and leased to non-district entity
- □ Owned by District, part used by district, part leased to non-district entity
- ☐ Owned by non-district entity and leased to district

06/05/2023 10:50 AM Page 3 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building	g Information				
Page La	ast Modified: 02/28/2023				
	28. For which of the following purposes is the building currently used? (check all that apply)				
	☑ Used for student instructional purposes				
	□ Used for district administration				
	□ Used for other district purposes				
	☐ Used by other organization(s)				
D:1.4:	no Hanna				
Bullai	ng Users				
	29. How many students were registered to receive instruction				
	"0") and skip to "Program Spaces" section. (Do not include	eve	ning class students)		
	863				
	30. Of these registered students, how many receive most of	the	ir instruction in:		
			Quantity		
	Permanent instructional spaces (i.e., regular classrooms)		863		
	Temporary instructional spaces (i.e., portable or demountable classroc attached to the building	ms)	0		
	Non-instructional spaces used as instructional spaces		0		
	31. If the answer is greater than zero, which types of non-ins	tru	ctional spaces were being used for instructional		
	purposes on October 1, 2019? (check all that apply)				
	□ Cafeteria				
	□ Gymnasium				
	□ Administrative Spaces				
	□ Library				
	□ Lobby				
	□ Stairwell				
	□ Storage space				
	□ Other (please describe)				
	☑ None				
	32. Grades Housed				
	□ Pre-K	⊌	7th		
	□ Kindergarten		8th		
	□ 1st		9th		
	□ 2nd		10th		
	□ 3rd	₩.	11th		

06/05/2023 10:50 AM Page 4 of 59

✓ 12th☐ N/A (none)

□ 4th

□ 5th☑ 6th

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Ruilding	Information	٦
Dullullu	IIIIOIIIIalioi	ı

Page L

Last Modified: 02/28/2023
33. For how many instructional days during the school year prior to the BCS assigned year (July 1 through June
30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none,
enter "0")
0
34. Is the building used for instructional purposes in the summer?
□ Yes
☑ No

Page 5 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

(No Response)

Progra	m Spaces	•			
Page L	Page Last Modified: 02/17/2023				
Progr	am Spaces				
	35. Number of instructional classrooms:				
	1				
	36. Gross square footage of all instruction	al classrooms (combined):			
	535.00	(00.000)			
	37. Other spaces provided:				
	□ a. N/A (none)	☐ j. Health Office	□ s. Resource Rooms		
	□ b. Administration	□ k. Home & Careers	□ t. Science Labs		
	□ c. Art	☐ I. Kitchen	□ u. Special Education		
	□ d. Audio Visual	□ m. Large Group Instruction	□ v. Swimming Pool		
	□ e. Auditorium	□ n. Library	□ w. Teacher Resource		
	□ f. Cafeteria	□ o. Multipurpose Rooms	□ x. Technology/Shop		
	☐ g. Computer Room	□ p. Music	☑ y. Other (please describe)		
	□ h. Guidance	□ q. Pre-K			
	☑ i. Gymnasium	□ r. Remedial Rooms			
	37a. Describe other spaces				
	Weight Room				
Space	e Adequacy				
	38. Rating of space adequacy:				
	☑ Good				
	□ Fair				
	□ Poor				
	38a Enter comments:				

06/05/2023 10:50 AM Page 6 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

- · ·			
Site	lti	liti	00

Page Last	Modified:	02/28/2023
-----------	-----------	------------

SITE UTILITIES	SIT	Έ	UT	ΊLΙ	Π	ES
----------------	-----	---	----	-----	---	----

UTILITIES	
39. Water	(н)
□ No	
	39a. Type of Service:
	✓ Municipal or Utility provided
	□ Well
	_ Other
	39b. Types of water service piping
	☑ Iron
	□ Galvanized
	☑ Copper
	□ Lead
	□ PVC
	□ Other
	□ N/A (None)
	39c. Overall condition of water service piping
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	39d. Year of Last Major Reconstruction/Replacement:
	2021
	39e. Expected Remaining Useful Life (Years):
	20
	39f. Cost to Reconstruct/Replace \$:
	(No Response)
	39g. Comments:
	(No Response)
40. Site Sa	nitary (H)
□ No	

06/05/2023 10:50 AM Page 7 of 59

Status Date: 02/28/2023 09:27 PM - Submitted

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

- · ·			
Site	lti	liti	00

Page Last Modified: 02/28/2023

	40a. Type of Service:
	☑ Municipal or utility sewer
	□ Site septic
	□ Other
	40b. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	40c. Year of Last Major Reconstruction/Replacement:
	2020
	40d. Expected Remaining Useful Life (Years):
	30
	40e. Cost to reconstruct/Replace \$: (No Response)
	(No Response)
	40f. Comments:
	(No Response)
41. Site Ga	is .
□ Yes	
☑ No	
42. Site Fu	el Oil
☑ Yes	
□ No	
	42a. Number of Above-Ground Tanks:
	1
	40a 4 Canacity of Above Crown d Tanks (mallana).
	42a.1 Capacity of Above-Ground Tanks (gallons): 8,000
	42b. Number of Below-Ground Tanks:
	0
	42b.1 Capacity of Below-Ground Tanks (gallons):
	0

06/05/2023 10:50 AM Page 8 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Site		14;	1:4:	
Site	U.	π	ш	es

Page Last M	odified: 02	/28/2023
-------------	-------------	----------

	42c. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	□ N/A
	42d. Year of Last Major Reconstruction/Replacement: 2022
	2022
	42e. Expected Remaining Useful Life (Years):
	15
	42f. Cost to Reconstruct/Replace \$:
	(No Response)
	42g. Comments:
	2,000 AST removed in 2022 and replaced with new 8,000 AST
43. Site Ele	ectrical, Including Exterior Distribution
✓ Yes	
□ No	
	43a. Service Provider:
	✓ Municipal or utility provided
	□ Self-Generated
	□ Other
	□ N/A
	42h Tuno of Convince
	43b. Type of Service:
	□ Above Ground
	☑ Below Ground
	□ N/A
	43c. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	43d. Year of Last Major Reconstruction/Replacement:
	2021

06/05/2023 10:50 AM Page 9 of 59

✓ No

Status Date: 02/28/2023 09:27 PM - Submitted

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Site		l+i	liti	^
OIIE.	ι	ЛI	ш	55

Site Uti	lities	
Page L	ast Modifie	ed: 02/28/2023
		43e. Expected Remaining Useful Life (Years):
		43f. Cost to Reconstruct/Replace \$: (No Response)
		43g. Comments: (No Response)
SITE	FEATURE	s
	44. Closed	Drainage Pipe Stormwater Management System
	44a. Does	s this facility have a closed pipe system?
	☑ Yes	
		44b. Condition: □ Excellent □ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure
		44c. Year of Last Major Reconstruction/Replacement:
		44d. Expected Remaining Useful Life (Years):
		44e. Cost to Reconstruct/Replace \$: (No Response)
		44f. Comments: (No Response)
	45. Open [Orainage Pipe Stormwater Management System
	45a. Does	this facility have an open stormwater system (ditch)?
	□ Yes	

Page 10 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Site	- 1	4:1	

Page Last	Modified:	02/28/2023
-----------	-----------	------------

zaot modilio	02/20/2020
46. Catch Ba	asins/Drop Inlets/Manholes
46a. Does t	his facility have catch basins/drop inlets/manholes?
✓ Yes	
□ No	
4	16b. Condition:
	□ Excellent
E	2 Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
4	46c. Year of Last Major Reconstruction/Replacement:
	2020
4	46d. Expected Remaining Useful Life (Years):
	20
	450 Cont to Becometwick/Bonless &
	46e. Cost to Reconstruct/Replace \$: No Response)
	46f. Comments:
	No Response)
47. Culverts	
47a. Does t	his facility have culverts?
□ Yes	
☑ No	
48. Outfalls	
48a Doos t	his facility have outfalls?
	identify that a dutumo.
☐ Yes	

49. Infiltration Basins/Chambers

49a. Does this facility have infiltration basins/chambers?

□ Yes☑ No

✓ No

06/05/2023 10:50 AM Page 11 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

C :	4-	14:1	1:4:	es
. `	16	ш	ш	ω

Page La	ast Mod	ified: 02	2/28/2023
---------	---------	-----------	-----------

□ Not Applicable

50. Retention Basins
50a. Does this facility have retention basins?
□ Yes
☑ No
51. Wetponds
51a. Does this facility have wetponds?
□ Yes
☑ No
52. Manufactured Stormwater Proprietary Units
52a. Does this facility have proprietary units?
□ Yes
☑ No
53. Point of Outfall Discharge: (check all that apply)
✓ Municipal storm sewer system
□ Combined sewer system
□ Surface Water
□ On-site recharge
□ Other (describe)
□ Not Applicable
54 Outfall Bassacian and Inventors
54. Outfall Reconnaissance Inventory
Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?
□ Yes
☑ No

06/05/2023 10:50 AM Page 12 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Other Site Features	
---------------------	--

Daga	Lact	Modified:	02/28/202	2
Page	Last	woallea:	02/28/202	23

SITE FEATURES

55. Pave	ement (Roadways and Parking Lots)
□ No	
	FF. Two (checkellallateranch)
	55a. Type: (check all that apply)
	□ Concrete
	☑ Asphalt
	☑ Gravel □ Other
	55b. Condition:
	□ Excellent
	□ Satisfactory
	☑ Unsatisfactory
	□ Non-Functioning □ Critical Failure
	55c. Year of Last Major Reconstruction/Replacement: 2020
	55d. Expected Remaining Useful Life (Years):
	10
	55e. Cost to Reconstruct/Replace \$:
	20,000.00
	55f. Comments:
	Section of southern perimeter cracked and in disrepair
56. Side	
✓ Yes	
□ No	
Ц 140	
	56a. Type: (check all that apply)
	□ Asphalt
	☑ Concrete
	□ Gravel
	□ Paver
	□ Other

06/05/2023 10:50 AM Page 13 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

O	ther	Site	Features
v	เมเตม	C)IIC	i caluico

Page Last Modified: 02/28/2023

	56b. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	56c. Year of Last Major Reconstruction/Replacement:
	2020
	56d. Expected Remaining Useful Life (Years):
	20
	56e. Cost to Reconstruct/Replace \$:
	(No Response)
	ECS Comments.
	56f. Comments: (No Response)
57. Playgro	ounds and Playground Equipment
□ Yes	
☑ No	
58. Athletic	c Fields and Play Fields
□ Yes	
☑ No	
59. Exterio	or Bleachers / Stadiums
□ Yes	
☑ No	
60 Related	d Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)
	2 Charles (Cach ac 1 1000 Doxes, Dagouts, Ollifoling Halls, Cto.)
□ Yes	
☑ No	

06/05/2023 10:50 AM Page 14 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

		•
Buil	ldina	Structure

Page	Last	Modified:	02/	17/202
raye	Lası	Modified.	02/	11/202

Building Structure	В	uil	dir	q	Str	uc	tur	е
---------------------------	---	-----	-----	---	-----	----	-----	---

61. Foundation (S)

61a. Ty	/pe (check all that apply):
	forced Concrete
	onry on Concrete Footing
□ Othe	r (specify)
	61a1. If "Other" please specify
	(No Response)
	61b. Evidence of structural concerns (check all that apply):
	□ Structural Cracks
	□ Heaving/Jacking
	□ Decay/Corrosion
	□ Water Penetration
	□ Unsupported Ends
	□ Other
	☑ None
	61c. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	61d. Year of Last Major Reconstruction/Replacement:
	2021
	61e. Expected Remaining Useful Life (Years):
	50
	61f. Cost to Reconstruct/Replace \$:
	0.00
	61g. Comments:
	(No Response)
62. Piei	rs (S)
	<u> </u>
☐ Yes	

06/05/2023 10:50 AM Page 15 of 59

2022 BUILDING	CONDITION SURVEY - 2022 - 0-001-MSHSGym
Building Structure	
Page Last Modifie	d: 02/17/2023
	62f. Cost to Reconstruct/Replace \$: (No Response)
	(NO Nesponse)
63. Columi	ns (S)
Type (che	ck all that apply):
□ Concrete	
✓ Masonry	
☑ Steel	
□ Stone	
□ Wood	
□ Other (sp	ecify)
□ N/A (Non	е)
	63.1. If "Other" please specify
	(No Response)
	63a. Evidence of structural concerns (check all that apply)
	□ Structural Cracks
	☐ Heaving/Jacking
	□ Decay/Corrosion
	□ Water Penetration
	□ Unsupported Ends
	□ Other
	☑ None
	63b. Condition:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure

63c. Year of Last Major Reconstruction/Replacement

2021

63d. Expected Remaining Useful Life (Years):

50

63e. Cost to Reconstruct/Replace \$:

0.00

63f. Comments:

(No Response)

06/05/2023 10:50 AM Page 16 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym
Building Structure
Page Last Modified: 02/17/2023
64. Footings (S)
Time (alocale all that south)
Type (check all that apply):
☑ Concrete
□ Other (specify)
64a. Evidence of structural concerns (check all that apply)
□ Structural Cracks
☐ Heaving/Jacking
□ Decay/Corrosion
□ Water Penetration
☐ Unsupported Ends
□ Other (specify)
☑ None
64.a1. If "Other" please specify
(No Response)
64b. Condition:
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure
64c. Year of Last Major Reconstruction/Replacement
2021
64d. Expected Remaining Useful Life (Years):

50

64e. Cost to Reconstruct/Replace \$:

0

64f. Comments:

(No Response)

06/05/2023 10:50 AM Page 17 of 59

202

☑ Satisfactory □ Unsatisfactory □ Non-Functioning □ Critical Failure

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym Building Structure		
Page Last Modified: 02/17/2023		
65. Structural Floors (S)		
65a. Type (check all that apply):		
□ Concrete Deck on Wood Structure		
□ Concrete/Metal Deck/Metal Joists		
□ Cast in Place Concrete Structural System		
□ Precast Concrete Structural System		
☑ Reinforced Concrete Slab on Grade		
□ Wood Deck on Wood Trusses		
□ Wood Deck on Wood Joists		
□ Other (specify)		
65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check a		
that apply):		
□ Structural Cracks		
☐ Unsupported Ends		
□ Rot/Decay/Corrosion		
□ Deflection		
□ Seriously Damaged/Missing Components		
□ Other Problems		
✓ None		
65b.1 Describe Other Problems:		
(No Response)		
65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):		
□ Cracks		
□ Deflection		
□ Rot/Decay/Corrosion		
✓ None		
65d. Overall Condition of Structural Floors:		
□ Excellent		

65e. Year of Last Major Reconstruction/Replacement: 2021

06/05/2023 10:50 AM Page 18 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Structure

Page Last Modified: 02/17/2023

65f. Expected Remaining Useful Life (Years):

50

65g. Cost to Reconstruct/Replace \$:

0.00

65h. Comments:

(No Response)

06/05/2023 10:50 AM Page 19 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

D	Idina	L n 10	-
DIII	16 311 16 3	Enve	I()()(-
			.000

Page Last Modified: 02/28/2023

BUILDING ENVELOPE

66. Exterior Walls/Columns (S)

☑ Alumir	num/Glass Curtain Wall
☑ Brick	
□ Concr	ete
□ Comp	posite Insulated Panels
Masor	nry
Steel	
□ Wood	
□ Other	(specify)
	66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.)
	(check all that apply):
	□ Structural Cracks
	□ Rot/Decay/Corrosion
	□ Other Problems
	☑ None
	66b.1 Describe Other Problems:
	(No Response)
	66c. Evidence of Concerns with Exterior Cladding (check all that apply):
	□ Cracks/Gaps
	□ Inadequate Flashing □ Efflorescence
	□ Efflorescence □ Moisture Penetration
	□ Rot/Decay/Corrosion
	□ Other Problems
	✓ None
	CCa 4 Decaribe Other Brokleme
	66c.1 Describe Other Problems: (No Response)
	66d. Overall Condition of Exterior Walls/Columns:
	□ Excellent
	☑ Satisfactory
	☑ Satisfactory

06/05/2023 10:50 AM Page 20 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Bui	lding	Enve	lope

Page Last	Modified:	02/28	/2023
-----------	-----------	-------	-------

	66e. Year of Last Major Reconstruction/Replacement:
	2021
	66f. Expected Remaining Useful Life (Years):
	50
	66g. Cost to Reconstruct/Replace \$:
	0.00
	66h. Comments:
	(No Response)
67. Chimn	eys (S)
□ No	
	67a. Material (check all that apply):
	□ Masonry
	□ Concrete
	☑ Metal
	□ Wood
	□ Other
	67a.1 Specify other:
	(No Response)
	67b. Overall Condition of Chimneys:
	Excellent
	☑ Satisfactory☐ Unsatisfactory
	□ Non-Functioning
	□ Critical failure
	Citical failure
	67c. Year of Last Major Reconstruction/Replacement:
	1972
	67.d Expected Remaining Useful Life (Years):
	10
	67e. Cost to Reconstruct/Replace \$:
	(No Response)
	67f. Comments:
	(No Response)

06/05/2023 10:50 AM Page 21 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGYM
Building Envelope
Page Last Modified: 02/28/2023
68. Parapets (S)
□ No
68a. Construction Type (check all that apply):
☑ Masonry
□ Concrete
□ Metal
□ Wood
□ Other (specify)
68a.1 Specify Other:
(No Response)
68b. Overall condition of parapets:
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure
68c. Year of Last Major Reconstruction/Replacement:
68d. Expected Remaining Useful Life (Years):
50
68e. Cost to Reconstruct/Replace \$:
0.00
68f. Comments:
(No Response)
69. Exterior Doors
69a. Overall Condition of Exterior Door Units:
□ Excellent
D Satisfactory

□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure

Page 22 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

D::i	Idina	Enve	lana
Dui	ıuırıu		IODE

Page Last Modified: 02/28/2023

	69b. Do any exterior doors have magnetic locking devices?
	☑ Yes
	□ No
	One Onfate/One with factors and allowed O
	69c. Safety/Security features are adequate?
	☑ Yes
	□ No
	69d. Year of Last Major Reconstruction/Replacement:
	2021
	69e. Expected Remaining Useful Life (Years):
	10
	69f. Cost to Reconstruct/Replace \$:
	10,000.00
	69g. Comments:
	Replace two (2) egress doors at west elevation of original gym.
70. Exterio	or Steps, Stairs, Ramps (S)
	r crope, crame, rrampe (e)
☑ Yes	
□ No	
	70a. Construction Type (Check all that apply)
	☑ Concrete
	□ Paver
	□ Steel
	□ Wood
	□ Other (specify)
	70b. If "other", specify here
	(No Response)
	70c. Overall Condition of Exterior Steps, Stairs and Ramps
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	70d. Year of Last Major Reconstruction/Replacement:
	1072

06/05/2023 10:50 AM Page 23 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Envelope	e e e e e e e e e e e e e e e e e e e
Page Last Modifie	ed: 02/28/2023
	70e. Expected Remaining Useful Life (Years):
	10
	70f. Cost to Reconstruct/Replace \$:
	3,000.00
	70g. Comments:
	Install handrail at exterior step at west side of original gym.
71. Fire Es	
	s This Facility Have One or More Fire Escapes?
□ Yes	
☑ No	
72. Windo	ws
✓ Yes	
□ No	
	72a. Window Material: (check all that apply)
	☑ Aluminum
	□ Steel
	☑ Vinyl
	□ Solid Wood
	□ Wood w/ External Cladding System
	□ Other
	72a1. If "Other" please specify
	(No Response)
	72b. Overall Condition of Windows:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure

06/05/2023 10:50 AM Page 24 of 59

72c. All Rescue Windows are Operable:

✓ Yes□ No□ N/A

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

n:	م مناما	Enve	
RIII	161111161	F NVA	icht ich

Page I	Last I	Modified:	02/	/28	20	23
--------	--------	-----------	-----	-----	----	----

72d. Year of Last Major Reconstruction/Replacement:	
2021	
72e. Expected Remaining Useful Life (Years):	
20	
72f. Cost to Reconstruct/Replace \$:	
0.00	
72g. Comments:	
(No Response)	
73. Roof and Skylights (S)	
✓ Yes	
□ No	
73a. Type of roof construction (check all that apply):	
□ Concrete on metal deck on metal trusses/joists	
□ Concrete (poured or plank) on concrete beams	
☐ Gypsum (poured or plank) on metal trusses/joists	
☑ Metal deck on metal trusses/joists	
□ Wood deck on wood trusses/joists	
□ Wood deck on metal trusses/joists	
□ Tectum on metal trusses/joists	
□ Other (describe below)	
73a.1 Other roof construction type:	
(No Response)	
73b. Type of roofing material (check all that apply):	
☑ Single-ply membrane	
□ Built-up	
☑ Asphalt shingle	
□ Pre-formed metal	
□ IRMA	
□ Slate	
□ Fluid applied seamless surfacing	
☐ Other (describe below)	
73b.1 Other roofing material:	
(No Response)	

06/05/2023 10:50 AM Page 25 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Danania Livolopo	Buildi	ng	Env	elo	g	е
------------------	--------	----	-----	-----	---	---

Page Last Modified: 02/28/2023

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all
that apply):
□ Structural cracks
□ Unsupported ends
□ Rot/Decay/Corrosion
□ Deflection
□ Seriously damaged/missing components
□ Other concerns (describe)
☑ None
73c.1 Describe other concerns:
(No Response)
73d. Evidence of structural concerns with roof deck (check all that apply):
□ Cracks
□ Deflection
□ Rot/Decay/Corrosion
☑ None
73e. Does this facility have skylights?
73e. Does this facility have skylights?
☑ Yes
□ No
73f. Skylight material (check all that apply):
☑ Plastic
□ Glass
□ Other
□ N/A
73g. Overall condition of skylights:
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure

06/05/2023 10:50 AM Page 26 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Envelope

Page Last Modified: 02/28/2023

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):
□ Failures/Splits/Cracks
□ Rot/Decay/Corrosion
□ Inadequate flashing/curbs/pitch pockets
□ Inadequate or poorly functioning roof drains
□ Evidence of water penetration/active leaks
□ Other (specify)
☑ None
70h A Chaoife athan annsana
73h.1 Specify other concerns: (No Response)
(No ixesponse)
73i. Overall Condition of Roof and Skylights:
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure
73j. Year of Last Major Reconstruction/Replacement:
2021
73k. Expected Remaining Useful Life (Years):
73I. Cost to Reconstruct/Replace \$:
92,400.00
72m Comments
73m. Comments:
Replace low asphalt shingle roof and skylights at original gym.

06/05/2023 10:50 AM Page 27 of 59

☑ Yes

06/05/2023 10:50 AM

Status Date: 02/28/2023 09:27 PM - Submitted

Page 28 of 59

	CONDITION SURVEY - 2022 - 0-001-MSHSGym
Building Interiors	ad. 02/20/2022
Page Last Modifie	ed: U2/28/2U23
BUILDING INTE	RIOR
74. Interio	r Bearing Walls and Fire Walls (S)
☑ Yes	
□ No	
	74a. Overall condition of interior bearing walls and fire walls:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-functioning
	□ Critical Failure
	74b. Year of Last Major Reconstruction/Replacement:
	2021
	74c. Expected Remaining Useful Life (Years):
	30
	74d. Cost to Reconstruct/Replace \$:
	(No Response)
	74e. Comments:
	(No Response)
	74.f Regulatory
	Have design professionals provided inventory of construction regulated under BCNYS Ch7, including
	assessment of their condition and maintenance, as required by NYSFC Ch7 and NYSPMC 703? This
	includes, but is not limited to:
	[check each item provided to the district]
	□ Fire-resistance rated assemblies;
	□ Smoke barriers and smoke partitions;
	Penetrations, joints, voids, door
	□ Assessment of Ch7 regulated assembly either damaged, altered, breached, or penetrated;
	Confirmation of compliant repair or protection of Ch7 regulated assembly either damaged, altered, breached, or
	penetrated; □ Other:
	74.f Other: (No Response)
75. Other I	Interior Walls

□ No

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Interiors			

Page Last Modified: 02/28/2023

	75a. Overall condition of other interior walls:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	75b. Year of Last Major Reconstruction/Replacement:
	2021
	75c. Expected Remaining Useful Life (Years):
	30
	75d Ocatita Danamaturat/Danilara ()
	75d. Cost to Reconstruct/Replace \$: (No Response)
	(140 Nesponse)
	75e. Comments:
	(No Response)
76. Carpet	
□ Yes	
☑ No	
77. Resilie	ent Tiles or Sheet Flooring
□ No	
	77. Whose leasted (shock all that apply).
	77a. Where located (check all that apply):
	□ Classrooms
	☑ Corridors
	☑ Offices
	□ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
	□ Other Areas
	77b. Overall condition of resilient tiles or sheet flooring:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	77c. Year of Last Major Reconstruction/Replacement:
	2021

06/05/2023 10:50 AM Page 29 of 59

79. Wood Flooring

✓ Yes□ No

Status Date: 02/28/2023 09:27 PM - Submitted

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

ZUZZ BUILDING	CONDITION 30KVL1 - 2022 - 0-001-M3H3GyIII
Building Interiors	
Page Last Modifie	ed: 02/28/2023
	77d. Expected Remaining Useful Life (Years):
	10
	77e. Cost to Reconstruct/Replace \$:
	(No Response)
	77f. Comments:
	(No Response)
78. Hard F	looring (concrete; ceramic tile; stone; etc)
□ No	
	78a. Where located (check all that apply):
	□ Classrooms
	□ Corridors
	□ Offices
	□ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
	□ Kitchen
	☑ Locker Rooms/Toilet Rooms
	□ Other Areas
	78b. Overall condition of hard flooring:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	78c. Year of Last Major Reconstruction/Replacement:
	2021
	78d. Expected Remaining Useful Life (Years):
	10
	78e. Cost to Reconstruct/Replace \$:
	(No Response)
	78f. Comments:
	/No Personal

06/05/2023 10:50 AM Page 30 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Bui	lding	Interiors
	9	

Page Last	Modified:	02/28/2023
-----------	-----------	------------

	79a. Where located (check all that apply):		
	□ Classrooms		
	□ Corridors		
	□ Offices		
	☑ Assembly Spaces (Auditorium, Gym, Play Room, etc.)		
	□ Other Areas		
	79b. Overall condition of wood flooring:		
	□ Excellent		
	☑ Satisfactory		
	□ Unsatisfactory		
	□ Non-Functioning		
	□ Critical Failure		
	79c. Year of Last Major Reconstruction/Replacement:		
	2022		
	79d. Expected Remaining Useful Life (Years):		
	10		
	79e. Cost to Reconstruct/Replace \$:		
	(No Response)		
	79f. Comments:		
	Both gym floors refinished in 2022		
80. Ceiling	s (H)		
✓ Yes□ No			
LI NO			
	80a. Overall condition of ceilings:		
	□ Excellent		
	☑ Satisfactory		
	□ Unsatisfactory		
	□ Non-Functioning		
	□ Critical Failure		
	80b. Year of Last Major Reconstruction/Replacement:		
	2021		
	80c. Expected Remaining Useful Life (Years):		
	10		
	20d Coot to Decemptive t/Depless C.		
	80d. Cost to Reconstruct/Replace \$:		

Page 31 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Duildina	Intorioro
Dullalla	Interiors

Daga	Lact	Modified:	02/28/2023	2
Page	Last	woallea:	02/28/2023	5

ast Modifie	ed: 02/28/2023		
	80e. Comments:		
	Repair gypsum ceiling in Girl's Locker Room Bathroom (Old Gym Building).		
	Replace ACT ceiling in southwest Lobby to Old Gym (Including Lighting)		
81. Locker	s		
☑ Yes			
□ No			
_ 140			
	81a. Overall condition of lockers:		
	□ Excellent		
	☑ Satisfactory		
	□ Unsatisfactory		
	□ Non-Functioning		
	□ Critical Failure		
	81b. Year of Last Major Reconstruction/Replacement: 2021		
	94a Expected Remaining Heaful Life (Vegra):		
	81c. Expected Remaining Useful Life (Years):		
	81d. Cost to Reconstruct/Replace \$:		
	(No Response)		
	81e. Comments:		
	(No Response)		
82. Interior	Doors		
□ No			
	82a. Overall condition of interior door units:		
	□ Excellent		
	☑ Satisfactory		
	□ Unsatisfactory		
	□ Non-Functioning		
	□ Critical Failure		

Page 32 of 59 06/05/2023 10:50 AM

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Bui	lding	Interi	ors

Page Last Modified: 02/28/2023

	82b. Overall condition of interior door hardware:			
	□ Excellent			
	☑ Satisfactory			
	□ Unsatisfactory			
	□ Non-Functioning			
	□ Critical Failure			
	82c. Year of Last Major Reconstruction/Replacement:			
	2021			
	82d. Expected Remaining Useful Life (Years):			
	10			
	82e. Cost to Reconstruct/Replace \$:			
	22,500.00			
	82f. Comments:			
	Replace wood doors			
83. Interio	r Stairs (H)			
□ Yes				
☑ No				
84 Flevato	or, Lift, and Escalators (H)			
	or, Ent, and Espaiators (11)			
□ Yes				
M NO	☑ No			
85 Swimn	ning Pool and Swimming Pool Systems (H)			
	and a contained of control con			
□ Yes				
☑ No				
86 Interio	r Bleachers			
	i Diedoliei 3			
☑ Yes				
□ No				
	86a. Overall condition of interior bleachers:			
	□ Excellent			
	☑ Satisfactory			
	□ Unsatisfactory			
	□ Non-Functioning			
	□ Critical Failure			

06/05/2023 10:50 AM Page 33 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Building Interiors

Page Last Modified: 02/28/2023

86b. Year of Last Major Reconstruction/Replacement:

2022

86c. Expected Remaining Useful Life (Years):

10

86d. Cost to Reconstruct/Replace \$

(No Response)

86e. Comments:

3-tier in Old Gym. 10-tier New Gym

06/05/2023 10:50 AM Page 34 of 59

✓ Yes □ No

Status Date: 02/28/2023 09:27 PM - Submitted

	Systems	ONDITION SURVEY - 2022 - 0-001-MSHSGym
	ast Modified:	02/28/2023
HVAC	Systems	
	-	erating Systems (H)
	☑ Yes	
	□ No	
	87	7a. Heat generation source (check all that apply):
		Biomass
		Boiler / Hot Water
		Boiler / Steam
		Cogeneration Plant
		Electric
		Furnace / Forced Air
		Geothermal
		Heat Pump
		Unit Ventilation
		Other (describe below)
	8	7a.1 Other heat generation source:
		No Response)
	87	7b. Overall condition of heat generating systems:
		Excellent
		Satisfactory
		Unsatisfactory
		Non-Functioning
		Critical Failure
	87	7c. Year of Last Major Reconstruction/Replacement:
		997
	10	7d. Expected Remaining Useful Life (Years):
	IC	
	87	7e. Cost to Reconstruct/Replace \$:
	(N	lo Response)
	87	7f. Comments:
	(N	lo Response)
	88. Ventilation	on System (exhaust fans, etc) (H)
		,

06/05/2023 10:50 AM Page 35 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

HVAC Systems

Page Last Modified: 02/28/2023

	88a. Type of ventilation system (check all that apply)			
		Natural ventilation	☐ Heat pump	
		Central system	□ Split system/ variable refrigerant	
		Energy recovery ventilator	□ Powered relief air system	
	✓		☑ Gravity/barometric relief	
	✓	Unitary (UVs, FC/BC, PTAC)	☑ Other (specify)	
		Forced air furnace		
	88b. If "Other" i	please specify here		
	EXHAUST FANS			
	88c. Overall condition of ventilation systems			
	□ Excellent			
	☑ Satisfactory			
	□ Unsatisfactory			
	□ Non-functionin	g		
	□ Critical Failure			
	88d. Year of last major reconstruction/replacement			
	88e. Expected remaining useful life (years):			
	88f. Cost to reconstruct/replace \$: 56,000			
	88g. Comments			
	REPLACE (4) EXHAUST FANS ON ORIGINAL GYMNASIUM ROOF			
89. Mecha	nical Cooling / A	ir-Conditioning Systems		
☑ Yes				
□ No				
	89a. Types of m	nechanical cooling		
	□ Chiller/chilled v	water		
	□ Geothermal			
	☑ Air cooled			
	□ Water cooled			
	☑ DX/Split syster	m		
	☐ Heat pump			

06/05/2023 10:50 AM Page 36 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

HVAC Systems

Page Last Modified: 02/28/2023

	89b. Overall condition of cooling/air-conditioning systems:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	89c. Year of Last Major Reconstruction/Replacement:
	2021
	89d. Expected Remaining Useful Life (Years):
	15
	89e. Cost to Reconstruct/Replace \$:
	150,000.00
	89f. Comments:
	REPLACE 10-TON SPLIT SYSTEM SERVING EXERCISE ROOM
00 Dimed I	lection and Cooling Distribution Customer Bining Dumme Dedictors Commenters Trans. Inculation at
-	leating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc.
(H)	
☑ Yes	
□ No	
	90a. Overall condition of piped heating and cooling distribution systems:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	90b. Year of Last Major Reconstruction/Replacement:
	2021
	90c. Expected Remaining Useful Life (Years):
	20
	90d. Cost to Reconstruct/Replace \$:
	(No Response)
	90e. Comments:
	(No Response)

06/05/2023 10:50 AM Page 37 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

HVAC Systems

Page L	ast N	1odified:	02	/28/	/2023	3
--------	-------	-----------	----	------	-------	---

☑ Yes	
□ No	
	91a. Overall condition of ducted heating and cooling distribution systems:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	91b. Year of Last Major Reconstruction/Replacement:
	2021
	91c. Expected Remaining Useful Life (Years):
	20
	91d. Cost to Reconstruct/Replace \$:
	(No Response)
	(13.135)
	91e. Comments: (No Response)
00 111/4	91e. Comments: (No Response)
92. HVA	91e. Comments:
92. HVA ☑ Yes	91e. Comments: (No Response)
	91e. Comments: (No Response)
☑ Yes	91e. Comments: (No Response)
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system □ Pneumatic □ Electric
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC)
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC) Web based DDC
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC)
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC) Web based DDC
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC) Web based DDC 92b. Overall condition of control systems: Excellent Satisfactory
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC) Web based DDC 92b. Overall condition of control systems: Excellent Satisfactory Unsatisfactory
☑ Yes	91e. Comments: (No Response) C Control Systems (H) 92a. Type of control system Pneumatic Electric Digital Direct Control (DDC) Web based DDC 92b. Overall condition of control systems: Excellent Satisfactory

06/05/2023 10:50 AM Page 38 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

HVAC Systems

Page Last Modified: 02/28/2023

92d. Expected Remaining Useful Life (Years):

15

92e. Cost to Reconstruct/Replace \$:

(No Response)

92f. Comments:

(No Response)

06/05/2023 10:50 AM Page 39 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

(No Response)

94. Sanitary System (H)

✓ Yes□ No

ZUZZ L	DOILDING	CONDITION SURVET - 2022 - 0-001-MISTISGYIII
Plumb	ing System	ns
Page I	Last Modific	ed: 02/28/2023
PLUM	MBING	
	93. Water	Supply System (H)
	□ No	
		93a. Types of pipes (check all that apply):
		□ Asbestos/transite
		☑ Copper
		□ Galvanized
		☑ Iron
		□ Lead
		□ PVC/CPVC/PEX/Plastic
		□ Other (specify)
		93b. If "Other" please specify here
		(No Response)
		93c. Overall condition of water supply system:
		□ Excellent
		☑ Satisfactory
		□ Unsatisfactory
		□ Non-Functioning
		□ Critical Failure
		93d. Year of Last Major Reconstruction/Replacement:
		2021
		93e. Expected Remaining Useful Life (Years):
		30
		93f. Cost to Reconstruct/Replace \$:
		(No Response)
		93g. Comments:
		aug. comments.

06/05/2023 10:50 AM Page 40 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

DΙι	ımh	ina	SV	ste	me
PΙU	umu	ırıa	٥v	Stei	115

Page Last Modified: 02/28/2023

95. Storm

✓ Yes□ No

94a. Types of pipes (check all that apply):
☑ Iron
□ Galvanized
□ Copper
□ Glass/ceramic
□ PVC/CPVC/ABS/poly propylene/plastic
□ Lead
□ Other (specify)
94a1. If "Other" please specify
2021
94b. Types of special sanitary systems (Check all that apply)
□ Acid waste and vent
□ Grease interceptor
□ Oil separator
□ Pumping station
□ Sediment trap
□ Septic tank
□ Waste water treatment plant
94c. Overall condition of sanitary system:
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure
94d. Year of Last Major Reconstruction/Replacement:
2021
94e. Expected Remaining Useful Life (Years): 30
94f. Cost to Reconstruct/Replace \$:
(No Response)
94g. Comments:
(No Response)
Water Drainage System (H)

06/05/2023 10:50 AM Page 41 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

DI.	ما ممر	:	0		
ΓIU	IIIIL	ina	OV:	ડાણ	115

Page Last Modified: 02/28/2023

	95a. Types of pipes (check all that apply)
	☑ Iron
	□ Galvanized
	□ Copper
	□ Lead
	□ Plastic
	□ Other
	95a1. If "Other" please specify
	(No Response)
	95b. Overall condition of storm water drainage system
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	95c. Year of Last Major Reconstruction/Replacement
	2021
	95d. Expected Remaining Useful Life (Years) 30
	95e. Cost to Reconstruct/Replace \$:
	(No Response)
	95f. Comments:
	(No Response)
96. Hot Wa	ater Heaters (H)
☑ Yes	
□ No	
	96a. Type of fuel (check all that apply):
	□ Oil
	□ Natural Gas
	□ Electricity
	□ Propane
	☑ Other (specify)
	96b. If "Other" please specify
	INDIRECT HOT WATER HEATER COIL MOUNTED IN BOILER

06/05/2023 10:50 AM Page 42 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

	PΙι	ımb	ing	Syste	ems
--	-----	-----	-----	-------	-----

Page Last Modified: 02/28/2023

	96c. Overall condition of hot water heaters:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	96d. Year of Last Major Reconstruction/Replacement:
	1997
	96e. Expected Remaining Useful Life (Years):
	10
	96f. Cost to Reconstruct/Replace \$:
	5,500.00
	96g. Comments:
	REPORTED THAT THERE IS NO HOT WATER FLOW TO SHOWERS IN 2021 ADDITION
97 Plumh	ing Fixtures (H)
	inig i ixtures (ii)
☑ Yes	
□ No	
	97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	97b. Year of Last Major Reconstruction/Replacement:
	2021
	07. Europted Demoining Hosfull its (Verna).
	97c. Expected Remaining Useful Life (Years):
	97d. Cost to Reconstruct/Replace \$:
	(No Response)
	97e. Comments:
	(No Response)
98. Water	Outlets/Taps for Drinking/Cooking Purposes (H)
□ No	

06/05/2023 10:50 AM Page 43 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Plumbing Systems

Page Last Modified: 02/28/2023

98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep, ice
machines, etc).
□ Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
□ Critical Failure
98b. Year of last major reconstruction/replacement:
2021
98c. Expected remaining useful life (years):
30
98d. Cost to reconstruct/replace \$:
(No Response)
98e. Comments
(No Response)

06/05/2023 10:50 AM Page 44 of 59

✓ No

Status Date: 02/28/2023 09:27 PM - Submitted

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Fire Su	ppression Systems
Page La	ast Modified: 02/17/2023
Fire S	uppression Systems
	99. Fire Suppression System (H)
	□ Yes
	☑ No
	100. Kitchen Hoods (H)
	□ Yes

06/05/2023 10:50 AM Page 45 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

	E	lectrical	Systems
--	---	-----------	---------

Page l	Last I	Modified:	02/28/	2023
--------	--------	-----------	--------	------

ELECTRICAL SYSTEMS

CTRICAL S	YSTEMS
101. Electr	ical Power Distribution System (H)
□ No	
	101a. Electrical supply meets current needs:
	✓ Yes
	□ No
	101b. Condition of electrical power distribution system:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	101c. Year of last major reconstruction/replacement?
	2019
	404 - Expected remaining control life (control)
	101d. Expected remaining useful life (years): 30
	101e. Cost to reconstruct/replace:
	(No Response)
	101f. Comments:
	(No Response)
102. Lighti	ng Fixtures (H)
□ No	
	4000 Condition of limbting figures.
	102a. Condition of lighting figures:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-functioning
	□ Critical failure
	102b. Year of last major reconstruction/replacement:
	2019
	102c. Expected remaining useful life (years):
	10

06/05/2023 10:50 AM Page 46 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Electrical Systems
Page Last Modified: 02/28/2023
102d. Cost to reconstruct/replace: 131,012
102e. Comments
Upgrade lighting fixtures to LED type.
103. Emergency/ Exit Lighting Systems (H):
☑ Yes □ No
103a. Overall condition of emergency/exit lighting systems:
 □ Excellent ☑ Satisfactory □ Unsatisfactory
□ Non-functioning □ Critical failure
103b. Year of last manjor reconstruction/replacement: 2019
103c. Expected remaining useful life (years):
10 103d. Cost to reconstruct/replace: (No Response)
103e. Comments
(No Response)
104. Emergency or standby power system (H)
□ Yes ☑ No
105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)
☑ Yes
105a. Overall condition of fire alarm system:
□ Excellent □ Satisfactory

06/05/2023 10:50 AM Page 47 of 59

☐ Unsatisfactory☐ Non-functioning☐ Critical failure

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

	E	lectrical	l Systems
--	---	-----------	-----------

Page Last	Modified:	02/28/2023
-----------	-----------	------------

	405h Veer of loct major reconstruction/replacements
	105b. Year of last major reconstruction/replacement: 2019
	105c. Expected remaining useful life (years):
	20
	105d. Cost to reconstruct/replace:
	(No Response)
	105e. Comments
	(No Response)
106. Carb	on Monoxide Alarm System (H)
	(1)
□ Yes ☑ No	
M INO	
107. Com	muncation Systems (H)
☑ Yes	
□ No	
	107a. Type of communication system (check all that apply)
	☑ Public Address
	☑ Phones (VOIP)
	□ Phones (Cellular)
	□ Phones (other)
	□ Mass Notification
	□ Emergency voice communication fire alarm system
	□ Lockdown notification system
	☐ Other (eg. radio) (describe below)
	107b. If "Other" please describe (No Response)
	107c. Communication systems are adequate:
	☑ Yes
	□ No
	107d. Condition of communication system:
	□ Excellent
	☑ Satisfactory
	□ Unsatisfactory
	□ Non-functioning
	□ Critical failure

06/05/2023 10:50 AM Page 48 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Electrical Systems

Page Last Modified: 02/28/2023

107e. Year of last major reconstruction/replacement:

2019

107f. Expected remaining useful life:

20

107g. Cost to replace/reconstruct:

(No Response)

107h. Comments

(No Response)

06/05/2023 10:50 AM Page 49 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

	Student	Transpo	ortation	Facilities
--	---------	---------	----------	------------

Page Last Modified: 02/17/2023

Student Transportation Facilities

lent Transportation Facilities
108. Is this building a transportation facility
□ Yes
☑ No
109. Does this facility have a fuel dispensing system?
□ Yes
☑ No
110. Does this facility have vehicle lifts
□ Yes
☑ No
111. Does this facility have a bus wash system?
□ Yes
☑ No

06/05/2023 10:50 AM Page 50 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Accessi		

Page Last Modified: 02/17/2023

ACCESSIBILITY

112. Exterior Accessible Route to Building (H)

(No Response)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?				
☑ Yes				
□ No				
112a. Features provided for exterior accessible route (check all that apply)				
☑ Curb ramps				
☑ Exterior ramps				
☑ Handicap parking				
112b. Cost of improvements needed to provide exterior accessible route to building \$:				
(No Response)				
112c. Comment				
(No Response)				
113. Is there an exterior accessible route to recreational facilities?				
☑ Yes				
□ No				
113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:				
(No Response)				
113b. Comments				
(No Response)				
114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that				
apply)				
□ Playground and play equipment				
☑ Playfield(s)				
✓ Athletic Field(s)				
☑ Exterior Bleachers				
□ Bathroom Facilities				
□ Concession Stand				

06/05/2023 10:50 AM Page 51 of 59

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Accessibility				
Page Last Modified: 02/17/2023				
114b. Comments				
(No Response)				
115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)				
The layout of the building should allow people with disabilities to obtain materials or services and use the facilities				
without assistance. This should include access to general purpose and specialized classrooms, public assembly				
spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services				
include drinking fountains, telephones, and other amenities.				
Is there an interior accessible interior route as specified above?				
Yes ✓ Yes				
□ No				
115a. Cost of improvements needed to provide interior accessible route(s) as spcified above \$:				
(No Response)				
115b. Comments				
(No Response)				
116. Does this facility have interior spaces that meet accessibility standards (check all that apply)				
□ Classrooms				
□ Labs (science, art, technology, etc)				
□ Shops				
□ Main Office				

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

☑ Restrooms on each floor

□ Health Office☑ Gymnasium□ Cafeteria□ Auditorium□ Stage

116b. Comments

(No Response)

06/05/2023 10:50 AM Page 52 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Environment/Comfort/Health

Page Last Modified: 02/17/2023

ENVIRONMENT/COMFORT/HEALTH

117. General Appearance

117a. Overall Rating:			
☑ Good			
□ Fair			
□ Poor			
117b. Comments:			
(No Response)			
118. Cleanliness (H)			
118a. Overall Rating:			
□ Fair			
□ Poor			
118b. Comments:			
(No Response)			
119. Are there walk off mats; grills in the entryway?			
☑ Yes			
□ No			
119a. If yes: at least 6 feet long?			
□ Yes			
☑ No			
120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)			
□ Yes			
☑ No			
EL INU			
121. Lighting Quality (H):			
121a. Types of lighting in general purpose classrooms (check all that apply):			
□ Daylight (natural)			
☑ Not full spectrum			
□ Full spectrum			
☑ LED			
☑ Flourescent			
□ Other (describe)			

06/05/2023 10:50 AM Page 53 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Environment/Comfort/Health

Page Last Modified: 02/17/2023

	121b. Are there blinds in the classroom to prevent glare?			
		☑ Yes		
		□ No		
		121c. Overall Rating:		
		☑ Good		
		□ Fair		
		□ Poor		
		121d. Comments:		
		(No Response)		
122. Evidence of Vermin (H) 122a. Is there evidence of active infestations of(check all that apply)?				
	Rodents			
	□ Wood-boring or Wood-eating Insects			
	Cockroad			
	Other Ve	rmin		
Z	None			

06/05/2023 10:50 AM Page 54 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Indoor A	ndoor Air Quality				
Page La	st Modified: 02/26/2023				
Indoor	Air Quality				
1	123. Mold (H)				
1	1232 Is there visible mold or moldy eders?				
	123a. Is there visible mold or moldy odors?				
	∃ Yes ₹ No				
☑ No					
123b. Are any surfaces constructed of any of the following materials?					
☑ Paper-faced or gypsum products					
	☑ Cellulose products (typically ceiling tiles)				
□ Not Applicable					
123c. Is there evidence of water intrusion?					
□ Yes					
☑ No					
123d. Estimated cost of necessary improvements \$:					
	(No Response)				
123e. Comments: (No Response)					
1	I24. Humidity/Moisture (H)				
	124a. Overall rating of humidity/moisture condition in building:				
	2 Good				
] Fair				
	Poor				
	124b. Are any of the following found in/or around classroom areas (check all that apply)?				
	□ Active leaks in roof				
	 □ Active leaks in plumbing □ Moisture condensation 				
	□ Visible stains or water damage				
	☑ None				
124c. Are any of the following found in/or around other areas (check all that apply)?					
□ Active leaks in roof					
	□ Active leaks in plumbing				
	□ Moisture condensation				
	☑ Visible stains or water damage				
	□ None				

06/05/2023 10:50 AM Page 55 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Indoor Air Quality				
Page Last Modified: 02/26/2023				
125. Ventilation: fresh air intake locations, air filters, etc. (H)				
125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?				
□ Yes				
☑ No				
125b. Is there accumulated dirt, dust or debris around fresh air intakes?				
□ Yes				
☑ No				
125c. Are fresh air intakes free of blockage?				
☑ Yes				
□ No				
125d. Is accumulated dirt, dust or debris in ductwork?				
□ Yes				
☑ No				
125e. Are dampers functioning as designed?				
☑ Yes				
□ No				
125f. Condition of air filters:				
□ Good				
☑ Fair				
□ Poor				
125g. Outside air is adequate for occupant load:				
☑ Yes				
□ No				
125h. Rating of ventilation/indoor air quality:				
☑ Good				
□ Fair				
□ Poor				

125i. Comments:

(No Response)

06/05/2023 10:50 AM Page 56 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Indoor	Air	Quality	

Page Last	Modified:	02/26/2023
-----------	-----------	------------

126. Indoor Air Quality (IAQ) Plan (H)				
126a. Doe	126a. Does the school district use EPA's <i>Tools for Schools</i> program?			
□ Yes				
☑ No				
	126b. If No, is some other IAQ management plan used?			
	⊻ Yes			
	□ No			
	126c. Has the District assigned IAQ responsibilities to a designated individual?			
	☑ Yes			
	□ No			
	126c.1 If Yes, what is their job title?			
	Sr. Custodian			
127. Does	s the school practice Integrated Pest Management (IPM)? (H)			
☑ Yes				
□ No				
	127a. Is vegetation kept one foot away from the building?			
	☑ Yes			
	□ No			
	127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?			
	☑ Yes			
	□ No			
	127c. Is there a certified pesticide applicator on staff?			
	✓ Yes			
	□ No			
	127d. Are pesticides used in the building?			
	· Yes			
	□ No			
	127d.1 If Yes, how are they typically applied?			
	 ☑ Spot treatment ☐ Area wide treatments 			
	L 7100 Mide troublette			

06/05/2023 10:50 AM Page 57 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Indoor Air Quality					
Page Last Modified: 02/26/2023					
127e. Are pesticides used on the grounds?					
□ Yes					
☑ No					
127e.1 If Yes, was an emergency exemption granted by the Board of Education?					
□ Yes					
□ No					
128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?					
(H)					
□ Yes					
☑ No					
128a. Has the facility been tested for the presence of radon?					
□ Yes					
☑ No					
128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?					
□ Yes					
□ No					

128c.1 Describe other actions taken to mitigate elevated radon levels:

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

(No Response)

☐ Yes, other (describe)☐ No action taken

□ Yes, active mitigation system installed
 □ Yes, passive mitigation system made active
 □ Yes, ventilation controls (HVAC) adjusted

06/05/2023 10:50 AM Page 58 of 59

2022 BUILDING CONDITION SURVEY - 2022 - 0-001-MSHSGym

Page Last Modified: 02/17/2023

Emergency Shelter

129. Does this	building	serve as an	emergency	/ shelter?
----------------	----------	-------------	-----------	------------

□ Yes	
☑ No	

06/05/2023 10:50 AM Page 59 of 59