

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Information

Page Last Modified: 02/28/2023

Building Information

1. Name of school district

Rye Neck Union Free School District

2. SED District 8-Digit BEDS Code

66-19-01-03

3. Building Name:

Rye Neck Middle School-High School

4. SED 4-Digit Facility Code:

0002

5. Survey Inspection Date:

07/26/2022

6. Building 911 Address:

300 Hornidge Road

7. City:

Mamaroneck

8. Zip Code:

10543

9. Certificate of Occupancy Status:

- A - Annual
- T - Temporary
- N - None

10. Certificate of Occupancy Expiration Date:

01/01/2024

10a. Is this a manufactured building? (Relocatable, modular, portable)

- Yes
- No

11. Have there been renovations or construction in the building during the past 12 months?

- Yes
- No

12. Was major construction/renovation work since 2015 conducted when school was in session?

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Information

Page Last Modified: 02/28/2023

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)

15,000,000.00

14. Overall building rating (to be answered after the building inspection is complete)

- Excellent
- Satisfactory
- Unsatisfactory
- Failing

15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?

- Yes
- No

16. A/E Firm Name:

LAN Associates, EPAS, LLP

17. A/E Firm Address:

252 Main Street, Goshen, NY 10924

18. A/E Firm Phone Number:

8456150350

19. E-mail:

danielle.farrell@lanassociates.com

20. A/E Name:

Danielle L. Farrell, AIA

21. A/E License #:

039812

Building Age, Gross Square Footage and Maintenance Staff

22. Building Age

| | Year |
|-----------------------|---------------|
| Original Construction | 1958 |
| Addition #1 | 1970 |
| Addition #2 | 2002 |
| Addition #3 | 2022 |
| Addition #4 | (No Response) |
| Addition #5 | (No Response) |
| Addition #6 | (No Response) |

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Information

Page Last Modified: 02/28/2023

| | Year |
|-------------|---------------|
| Addition #7 | (No Response) |
| Addition #8 | (No Response) |
| Addition #9 | (No Response) |

23. Square feet of construction

| | Sq Feet |
|-----------------------|---------------|
| Original construction | 89,992.00 |
| Addition #1 | 9,346.00 |
| Addition #2 | 7,596.00 |
| Addition #3 | 24,341.00 |
| Addition #4 | (No Response) |
| Addition #5 | (No Response) |
| Addition #6 | (No Response) |
| Addition #7 | (No Response) |
| Addition #8 | (No Response) |
| Addition #9 | (No Response) |

24. Gross square ft. of Building as currently configured:

131,275

25. Number of Floors:

2

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

| | Count Employees |
|-----------------------|-----------------|
| Full-time custodians: | 9 |
| Part-time custodians: | 0 |
| Totals: | 9 |

Building Ownership and Occupancy Status

27. Building Ownership (check one):

- Owned and used by district
- Owned by District and leased to non-district entity
- Owned by District, part used by district, part leased to non-district entity
- Owned by non-district entity and leased to district

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Information

Page Last Modified: 02/28/2023

28. For which of the following purposes is the building currently used? (check all that apply)

- Used for student instructional purposes
- Used for district administration
- Used for other district purposes
- Used by other organization(s)

Building Users

29. How many students were registered to receive instruction in this building as of the last year? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

863

30. Of these registered students, how many receive most of their instruction in:

| | Quantity |
|--|----------|
| Permanent instructional spaces (i.e., regular classrooms) | 863 |
| Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building | 0 |
| Non-instructional spaces used as instructional spaces | 0 |

31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2019? (check all that apply)

- Cafeteria
- Gymnasium
- Administrative Spaces
- Library
- Lobby
- Stairwell
- Storage space
- Other (please describe)
- None

32. Grades Housed

- Pre-K
- Kindergarten
- 1st
- 2nd
- 3rd
- 4th
- 5th
- 6th
- 7th
- 8th
- 9th
- 10th
- 11th
- 12th
- N/A (none)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Information

Page Last Modified: 02/28/2023

33. For how many instructional days during the school year prior to the BCS assigned year (July 1 through June 30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

34. Is the building used for instructional purposes in the summer?

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Program Spaces

Page Last Modified: 02/28/2023

Program Spaces

35. Number of instructional classrooms:

57

36. Gross square footage of all instructional classrooms (combined):

46,800.00

37. Other spaces provided:

- | | | |
|---|--|--|
| <input type="checkbox"/> a. N/A (none) | <input checked="" type="checkbox"/> j. Health Office | <input checked="" type="checkbox"/> s. Resource Rooms |
| <input checked="" type="checkbox"/> b. Administration | <input checked="" type="checkbox"/> k. Home & Careers | <input checked="" type="checkbox"/> t. Science Labs |
| <input checked="" type="checkbox"/> c. Art | <input checked="" type="checkbox"/> l. Kitchen | <input checked="" type="checkbox"/> u. Special Education |
| <input checked="" type="checkbox"/> d. Audio Visual | <input checked="" type="checkbox"/> m. Large Group Instruction | <input type="checkbox"/> v. Swimming Pool |
| <input checked="" type="checkbox"/> e. Auditorium | <input checked="" type="checkbox"/> n. Library | <input checked="" type="checkbox"/> w. Teacher Resource |
| <input checked="" type="checkbox"/> f. Cafeteria | <input type="checkbox"/> o. Multipurpose Rooms | <input checked="" type="checkbox"/> x. Technology/Shop |
| <input checked="" type="checkbox"/> g. Computer Room | <input checked="" type="checkbox"/> p. Music | <input type="checkbox"/> y. Other (please describe) |
| <input checked="" type="checkbox"/> h. Guidance | <input type="checkbox"/> q. Pre-K | |
| <input type="checkbox"/> i. Gymnasium | <input checked="" type="checkbox"/> r. Remedial Rooms | |

37a. Describe other spaces

(No Response)

Space Adequacy

38. Rating of space adequacy:

- Good
- Fair
- Poor

38a. Enter comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

SITE UTILITIES

39. Water (H)

- Yes
- No

39a. Type of Service:

- Municipal or Utility provided
- Well
- Other

39b. Types of water service piping

- Iron
- Galvanized
- Copper
- Lead
- PVC
- Other
- N/A (None)

39c. Overall condition of water service piping

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

39d. Year of Last Major Reconstruction/Replacement:

2002

39e. Expected Remaining Useful Life (Years):

20

39f. Cost to Reconstruct/Replace \$:

(No Response)

39g. Comments:

(No Response)

40. Site Sanitary (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

40a. Type of Service:

- Municipal or utility sewer
- Site septic
- Other

40b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

40c. Year of Last Major Reconstruction/Replacement:

2021

40d. Expected Remaining Useful Life (Years):

30

40e. Cost to reconstruct/Replace \$:

(No Response)

40f. Comments:

(No Response)

41. Site Gas

- Yes
- No

41a. Type of gas service:

- Natural Gas
- Liquid Petroleum

41b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

41c. Year of Last Major Reconstruction/Replacement;

2013

41d. Expected Remaining Useful Life (Years):

25

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

41e. Cost to Reconstruct/Replace \$:

(No Response)

41f. Comments:

(No Response)

42. Site Fuel Oil

Yes

No

42a. Number of Above-Ground Tanks:

1

42a.1 Capacity of Above-Ground Tanks (gallons):

2,000

42b. Number of Below-Ground Tanks:

0

42b.1 Capacity of Below-Ground Tanks (gallons):

0

42c. Condition:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

N/A

42d. Year of Last Major Reconstruction/Replacement:

2000

42e. Expected Remaining Useful Life (Years):

15

42f. Cost to Reconstruct/Replace \$:

(No Response)

42g. Comments:

(No Response)

43. Site Electrical, Including Exterior Distribution

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

43a. Service Provider:

- Municipal or utility provided
- Self-Generated
- Other
- N/A

43b. Type of Service:

- Above Ground
- Below Ground
- N/A

43c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

43d. Year of Last Major Reconstruction/Replacement:

2001

43e. Expected Remaining Useful Life (Years):

20

43f. Cost to Reconstruct/Replace \$:

300,000.00

43g. Comments:

Utility equipment within building is not provided with adequate working space clearance and is in poor condition.

SITE FEATURES

44. Closed Drainage Pipe Stormwater Management System

44a. Does this facility have a closed pipe system?

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

44b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

2002

44d. Expected Remaining Useful Life (Years):

18

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

(No Response)

45. Open Drainage Pipe Stormwater Management System

45a. Does this facility have an open stormwater system (ditch)?

- Yes
- No

45b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

45c. Year of Last Major Reconstruction/Replacement:

2013

45d. Expected Remaining Useful Life (Years):

23

45e. Cost to Reconstruct/Replace \$:

(No Response)

45f. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

46. Catch Basins/Drop Inlets/Manholes

46a. Does this facility have catch basins/drop inlets/manholes?

- Yes
- No

46b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

46c. Year of Last Major Reconstruction/Replacement:

2002

46d. Expected Remaining Useful Life (Years):

10

46e. Cost to Reconstruct/Replace \$:

(No Response)

46f. Comments:

(No Response)

47. Culverts

47a. Does this facility have culverts?

- Yes
- No

47b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

47c. Year of Last Major Reconstruction/Replacement:

2002

47d. Expected Remaining Useful Life (Years):

10

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

47e. Cost to Reconstruct/Replace \$:

(No Response)

47f. Comments:

(No Response)

48. Outfalls

48a. Does this facility have outfalls?

Yes

No

48b. Condition:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

48c. Year of Last Major Reconstruction/Replacement:

2002

48d. Expected Remaining Useful Life (Years):

10

48e. Cost to Reconstruct/Replace \$:

(No Response)

48f. Comments:

(No Response)

49. Infiltration Basins/Chambers

49a. Does this facility have infiltration basins/chambers?

Yes

No

50. Retention Basins

50a. Does this facility have retention basins?

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Site Utilities

Page Last Modified: 02/28/2023

51. Wetponds

51a. Does this facility have wetponds?

- Yes
- No

52. Manufactured Stormwater Proprietary Units

52a. Does this facility have proprietary units?

- Yes
- No

53. Point of Outfall Discharge: (check all that apply)

- Municipal storm sewer system
- Combined sewer system
- Surface Water
- On-site recharge
- Other (describe)
- Not Applicable

53.a Please describe other:

Outfall to creek

54. Outfall Reconnaissance Inventory

Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?

- Yes
- No
- Not Applicable

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Other Site Features

Page Last Modified: 02/28/2023

SITE FEATURES

55. Pavement (Roadways and Parking Lots)

- Yes
- No

55a. Type: (check all that apply)

- Concrete
- Asphalt
- Gravel
- Other

55b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

55c. Year of Last Major Reconstruction/Replacement:

2022

55d. Expected Remaining Useful Life (Years):

20

55e. Cost to Reconstruct/Replace \$:

25,000.00

55f. Comments:

Sections throughout site cracked and in major disrepair

56. Sidewalks

- Yes
- No

56a. Type: (check all that apply)

- Asphalt
- Concrete
- Gravel
- Paver
- Other

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Other Site Features

Page Last Modified: 02/28/2023

56b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

56c. Year of Last Major Reconstruction/Replacement:

2022

56d. Expected Remaining Useful Life (Years):

35

56e. Cost to Reconstruct/Replace \$:

15,000.00

56f. Comments:

Overall satisfactory but several cracks in sections of sidewalk

57. Playgrounds and Playground Equipment

- Yes
- No

57a. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

57b. Year of Last Major Reconstruction/Replacement:

2007

57c. Expected Remaining Useful Life (Years):

10

57d. Cost to Reconstruct/Replace \$:

(No Response)

57e. Comments:

(No Response)

58. Athletic Fields and Play Fields

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Other Site Features

Page Last Modified: 02/28/2023

58a. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

58b. Year of Last Major Reconstruction/Replacement:

2001

58c. Expected Remaining Useful Life (Years):

10

58d. Cost to Reconstruct/Replace \$:

(No Response)

58e. Comments:

(No Response)

58f. Does the facility have synthetic turf field(s)

- Yes
- No

58f.1 If Yes, how many synthetic turf fields?

(No Response)

58f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):

(No Response)

58f.3 Type of synthetic turf field infill:

(No Response)

59. Exterior Bleachers / Stadiums

- Yes
- No

59a. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

59b. Year of Last Major Reconstruction/Replacement:

2001

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Other Site Features

Page Last Modified: 02/28/2023

59c. Expected Remaining Useful Life (Years):

10

59d. Cost to Reconstruct/Replace \$:

(No Response)

59e. Comments:

(No Response)

59f. Seating Capacity

(No Response)

60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)

Yes

No

60a. Condition:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

60b. Year of Last Major Reconstruction/Replacement:

2001

60c. Expected Remaining Useful Life (Years):

10

60d. Cost to Reconstruct/Replace \$:

(No Response)

60e. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

Building Structure

61. Foundation (S)

61a. Type (check all that apply):

- Reinforced Concrete
- Masonry on Concrete Footing
- Other (specify)

61a1. If "Other" please specify

(No Response)

61b. Evidence of structural concerns (check all that apply):

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

61c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

61d. Year of Last Major Reconstruction/Replacement:

2014

61e. Expected Remaining Useful Life (Years):

20

61f. Cost to Reconstruct/Replace \$:

5,000.00

61g. Comments:

Repair settlement and cracking of the foundation at the northeast corner of Wing E.

62. Piers (S)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

62a. Type (check all that apply)

- Concrete
- Masonry
- Steel
- Stone
- Wood
- Other (specify)
- N/A (none)

62a1. If "Other" please specify

(No Response)

62b. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

62c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

62d. Year of Last Major Reconstruction/Replacement

2022

62e. Expected Remaining Useful Life (Years):

60

62f. Cost to Reconstruct/Replace \$:

(No Response)

62g. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

63. Columns (S)

Type (check all that apply):

- Concrete
- Masonry
- Steel
- Stone
- Wood
- Other (specify)
- N/A (None)

63.1. If "Other" please specify

(No Response)

63a. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

63b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

63c. Year of Last Major Reconstruction/Replacement

2022

63d. Expected Remaining Useful Life (Years):

20

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

64. Footings (S)

Type (check all that apply):

- Concrete
- Other (specify)

64a. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other (specify)
- None

64.a1. If "Other" please specify

(No Response)

64b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

64c. Year of Last Major Reconstruction/Replacement

2022

64d. Expected Remaining Useful Life (Years):

20

64e. Cost to Reconstruct/Replace \$:

(No Response)

64f. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

65. Structural Floors (S)

65a. Type (check all that apply):

- Concrete Deck on Wood Structure
- Concrete/Metal Deck/Metal Joists
- Cast in Place Concrete Structural System
- Precast Concrete Structural System
- Reinforced Concrete Slab on Grade
- Wood Deck on Wood Trusses
- Wood Deck on Wood Joists
- Other (specify)

65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

- Structural Cracks
- Unsupported Ends
- Rot/Decay/Corrosion
- Deflection
- Seriously Damaged/Missing Components
- Other Problems
- None

65b.1 Describe Other Problems:

(No Response)

65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

65d. Overall Condition of Structural Floors:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

65e. Year of Last Major Reconstruction/Replacement:

2022

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Structure

Page Last Modified: 02/28/2023

65f. Expected Remaining Useful Life (Years):

2

65g. Cost to Reconstruct/Replace \$:

300,000.00

65h. Comments:

Inject structural foam under slab at E Wing

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

BUILDING ENVELOPE

66. Exterior Walls/Columns (S)

66a. Material (check all that apply):

- Aluminum/Glass Curtain Wall
- Brick
- Concrete
- Composite Insulated Panels
- Masonry
- Steel
- Wood
- Other (specify)

66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.)

(check all that apply):

- Structural Cracks
- Rot/Decay/Corrosion
- Other Problems
- None

66b.1 Describe Other Problems:

(No Response)

66c. Evidence of Concerns with Exterior Cladding (check all that apply):

- Cracks/Gaps
- Inadequate Flashing
- Efflorescence
- Moisture Penetration
- Rot/Decay/Corrosion
- Other Problems
- None

66c.1 Describe Other Problems:

(No Response)

66d. Overall Condition of Exterior Walls/Columns:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

66e. Year of Last Major Reconstruction/Replacement:

2022

66f. Expected Remaining Useful Life (Years):

20

66g. Cost to Reconstruct/Replace \$:

65,400.00

66h. Comments:

Repair/repaint exterior plywood soffits. Repair vertical cracking at the exit doors at north elevation of E Wing.

67. Chimneys (S)

Yes

No

67a. Material (check all that apply):

Masonry

Concrete

Metal

Wood

Other

67a.1 Specify other:

(No Response)

67b. Overall Condition of Chimneys:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical failure

67c. Year of Last Major Reconstruction/Replacement:

2013

67.d Expected Remaining Useful Life (Years):

15

67e. Cost to Reconstruct/Replace \$:

5,000.00

67f. Comments:

Repoint top of chimney.

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

68. Parapets (S)

- Yes
- No

69. Exterior Doors

69a. Overall Condition of Exterior Door Units:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

69b. Do any exterior doors have magnetic locking devices?

- Yes
- No

69c. Safety/Security features are adequate?

- Yes
- No

69d. Year of Last Major Reconstruction/Replacement:

2014

69e. Expected Remaining Useful Life (Years):

20

69f. Cost to Reconstruct/Replace \$:

80,500.00

69g. Comments:

Repair/replace various exterior door throughout facility.

70. Exterior Steps, Stairs, Ramps (S)

- Yes
- No

70a. Construction Type (Check all that apply)

- Concrete
- Paver
- Steel
- Wood
- Other (specify)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

70b. If "other", specify here

(No Response)

70c. Overall Condition of Exterior Steps, Stairs and Ramps

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

70d. Year of Last Major Reconstruction/Replacement:

2014

70e. Expected Remaining Useful Life (Years):

20

70f. Cost to Reconstruct/Replace \$:

(No Response)

70g. Comments:

(No Response)

71. Fire Escapes (S)

71a. Does This Facility Have One or More Fire Escapes?

- Yes
- No

72. Windows

- Yes
- No

72a. Window Material: (check all that apply)

- Aluminum
- Steel
- Vinyl
- Solid Wood
- Wood w/ External Cladding System
- Other

72a1. If "Other" please specify

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

72b. Overall Condition of Windows:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

72c. All Rescue Windows are Operable:

- Yes
- No
- N/A

72d. Year of Last Major Reconstruction/Replacement:

2022

72e. Expected Remaining Useful Life (Years):

15

72f. Cost to Reconstruct/Replace \$:

(No Response)

72g. Comments:

(No Response)

73. Roof and Skylights (S)

- Yes
- No

73a. Type of roof construction (check all that apply):

- Concrete on metal deck on metal trusses/joists
- Concrete (poured or plank) on concrete beams
- Gypsum (poured or plank) on metal trusses/joists
- Metal deck on metal trusses/joists
- Wood deck on wood trusses/joists
- Wood deck on metal trusses/joists
- Tectum on metal trusses/joists
- Other (describe below)

73a.1 Other roof construction type:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

73b. Type of roofing material (check all that apply):

- Single-ply membrane
- Built-up
- Asphalt shingle
- Pre-formed metal
- IRMA
- Slate
- Fluid applied seamless surfacing
- Other (describe below)

73b.1 Other roofing material:

(No Response)

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- Structural cracks
- Unsupported ends
- Rot/Decay/Corrosion
- Deflection
- Seriously damaged/missing components
- Other concerns (describe)
- None

73c.1 Describe other concerns:

(No Response)

73d. Evidence of structural concerns with roof deck (check all that apply):

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

73e. Does this facility have skylights?

- Yes
- No

73f. Skylight material (check all that apply):

- Plastic
- Glass
- Other
- N/A

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Envelope

Page Last Modified: 02/28/2023

73g. Overall condition of skylights:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- Failures/Splits/Cracks
- Rot/Decay/Corrosion
- Inadequate flashing/curbs/pitch pockets
- Inadequate or poorly functioning roof drains
- Evidence of water penetration/active leaks
- Other (specify)
- None

73h.1 Specify other concerns:

(No Response)

73i. Overall Condition of Roof and Skylights:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

73j. Year of Last Major Reconstruction/Replacement:

2022

73k. Expected Remaining Useful Life (Years):

10

73l. Cost to Reconstruct/Replace \$:

2,000.00

73m. Comments:

Replace one (1) damaged skylight on Wing E.

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

BUILDING INTERIOR

74. Interior Bearing Walls and Fire Walls (S)

- Yes
- No

74a. Overall condition of interior bearing walls and fire walls:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical Failure

74b. Year of Last Major Reconstruction/Replacement:

2022

74c. Expected Remaining Useful Life (Years):

15

74d. Cost to Reconstruct/Replace \$:

600,000.00

74e. Comments:

Remove Lexan windows in corridors in "A", "B" and "E" Wings infill wall

74.f Regulatory

Have design professionals provided inventory of construction regulated under BCNYS Ch7, including assessment of their condition and maintenance, as required by NYSFC Ch7 and NYSPMC 703? This includes, but is not limited to:

[check each item provided to the district]

- Fire-resistance rated assemblies;
- Smoke barriers and smoke partitions;
- Penetrations, joints, voids, door
- Assessment of Ch7 regulated assembly either damaged, altered, breached, or penetrated;
- Confirmation of compliant repair or protection of Ch7 regulated assembly either damaged, altered, breached, or penetrated;
- Other:

74.f Other:

(No Response)

75. Other Interior Walls

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

75a. Overall condition of other interior walls:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

2022

75c. Expected Remaining Useful Life (Years):

15

75d. Cost to Reconstruct/Replace \$:

(No Response)

75e. Comments:

(No Response)

76. Carpet

- Yes
- No

76a. Where located (check all that apply):

- Classrooms
- Corridors
- Offices
- Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Other Areas

76b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

76c. Year of Last Major Reconstruction/Replacement:

2022

76d. Expected Remaining Useful Life (Years):

5

76e. Cost to Reconstruct/Replace \$:

28,200.00

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

76f. Comments:

Replace Carpet in Main Office Waiting Room D6, Replace Carpet in "E" Wing Office Suite, Replace Carpet in IT Room L-103

77. Resilient Tiles or Sheet Flooring

- Yes
- No

77a. Where located (check all that apply):

- Classrooms
- Corridors
- Offices
- Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Other Areas

77b. Overall condition of resilient tiles or sheet flooring:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

2022

77d. Expected Remaining Useful Life (Years):

10

77e. Cost to Reconstruct/Replace \$:

221,625.00

77f. Comments:

Replace VCT tile in Art Room C-1, Replace VCT in "E" Corridor, Abate and Replace VAT in Supply Storage Room E8

78. Hard Flooring (concrete; ceramic tile; stone; etc)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

78a. Where located (check all that apply):

- Classrooms
- Corridors
- Offices
- Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Kitchen
- Locker Rooms/Toilet Rooms
- Other Areas

78b. Overall condition of hard flooring:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

78c. Year of Last Major Reconstruction/Replacement:

2022

78d. Expected Remaining Useful Life (Years):

15

78e. Cost to Reconstruct/Replace \$:

100,000.00

78f. Comments:

Renovate single occupancy bathrooms in the "E" Wing Office Suite

79. Wood Flooring

- Yes
- No

79a. Where located (check all that apply):

- Classrooms
- Corridors
- Offices
- Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Other Areas

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

79b. Overall condition of wood flooring:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

79c. Year of Last Major Reconstruction/Replacement:

2002

79d. Expected Remaining Useful Life (Years):

8

79e. Cost to Reconstruct/Replace \$:

74,000.00

79f. Comments:

Replace wood floors in Computer Lab B-6, Technology Room B-8, Tech/Video Room B-10E and Music Rooms B-10B and B-10C

80. Ceilings (H)

- Yes
- No

80a. Overall condition of ceilings:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

80b. Year of Last Major Reconstruction/Replacement:

2022

80c. Expected Remaining Useful Life (Years):

8

80d. Cost to Reconstruct/Replace \$:

185,250.00

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

80e. Comments:

Install ceiling in Computer Lab B-6, Technology Room B-8, Tech/Video Room B-10E and Music Rooms B-10B and B-10C (New Lighting)
Replace ceilings in IT Room L-103, Server Room L-104 (Replace Lighting)
Install new ceiling in Art Room C-1 (Replace Lighting)
Install new ceiling in Nurse's Suite (Replace Lighting)
Replace ceiling in "E" Wing Office Suite (Replace Lighting)
Install new ceiling in Supply Storage Room E8 (Replace Lighting)

81. Lockers

- Yes
- No

81a. Overall condition of lockers:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

81b. Year of Last Major Reconstruction/Replacement:

2022

81c. Expected Remaining Useful Life (Years):

10

81d. Cost to Reconstruct/Replace \$:

(No Response)

81e. Comments:

(No Response)

82. Interior Doors

- Yes
- No

82a. Overall condition of interior door units:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

82b. Overall condition of interior door hardware:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

2022

82d. Expected Remaining Useful Life (Years):

10

82e. Cost to Reconstruct/Replace \$:

(No Response)

82f. Comments:

(No Response)

83. Interior Stairs (H)

- Yes
- No

83a. Overall condition of interior stairs:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

83b. Stair material

- Concrete
- Steel
- Wood
- Other

83c. Year of Last Major Reconstruction/Replacement:

2022

83d. Expected Remaining Useful Life (Years):

20

83e. Cost to Reconstruct/Replace \$:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Building Interiors

Page Last Modified: 02/28/2023

83f. Comments:

(No Response)

84. Elevator, Lift, and Escalators (H)

Yes

No

84a. Overall condition of elevators, lifts, escalators:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

84b. Year of Last Major Reconstruction/Replacement:

2022

84c. Expected Remaining Useful Life (Years):

15

84d. Cost to Reconstruct/Replace \$

(No Response)

84e. Comments:

(No Response)

85. Swimming Pool and Swimming Pool Systems (H)

Yes

No

86. Interior Bleachers

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

HVAC Systems

Page Last Modified: 02/28/2023

HVAC Systems

87. Heat Generating Systems (H)

- Yes
- No

87a. Heat generation source (check all that apply):

- Biomass
- Boiler / Hot Water
- Boiler / Steam
- Cogeneration Plant
- Electric
- Furnace / Forced Air
- Geothermal
- Heat Pump
- Unit Ventilation
- Other (describe below)

87a.1 Other heat generation source:

(No Response)

87b. Overall condition of heat generating systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2022

87d. Expected Remaining Useful Life (Years):

20

87e. Cost to Reconstruct/Replace \$:

11,620,000.00

87f. Comments:

REPLACE GAS FIRED PACKAGED ROOFTOP UNITS THAT HAVE SURPASSED SERVICE LIFE

88. Ventilation System (exhaust fans, etc) (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

HVAC Systems

Page Last Modified: 02/28/2023

88a. Type of ventilation system (check all that apply)

| | |
|---|---|
| <input checked="" type="checkbox"/> Natural ventilation | <input type="checkbox"/> Heat pump |
| <input type="checkbox"/> Central system | <input type="checkbox"/> Split system/ variable refrigerant |
| <input type="checkbox"/> Energy recovery ventilator | <input type="checkbox"/> Powered relief air system |
| <input checked="" type="checkbox"/> Rooftop units | <input checked="" type="checkbox"/> Gravity/barometric relief |
| <input type="checkbox"/> Unitary (UVs, FC/BC, PTAC) | <input checked="" type="checkbox"/> Other (specify) |
| <input type="checkbox"/> Forced air furnace | |

88b. If "Other" please specify here

EXHAUST FANS

88c. Overall condition of ventilation systems

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical Failure

88d. Year of last major reconstruction/replacement

2022

88e. Expected remaining useful life (years):

20

88f. Cost to reconstruct/replace \$:

11,620,000.00

88g. Comments

REPLACE AGED ROOFTOP UNITS & EXHAUST FANS. ADD UNIT VENTS & FAN COILS WITH AC.

89. Mechanical Cooling / Air-Conditioning Systems

Yes

No

89a. Types of mechanical cooling

Chiller/chilled water

Geothermal

Air cooled

Water cooled

DX/Split system

Heat pump

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

HVAC Systems

Page Last Modified: 02/28/2023

89b. Overall condition of cooling/air-conditioning systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

89c. Year of Last Major Reconstruction/Replacement:

2022

89d. Expected Remaining Useful Life (Years):

20

89e. Cost to Reconstruct/Replace \$:

11,620,000.00

89f. Comments:

REPLACE AGED ROOFTOP UNITS. ADD AC TO CLASSROOMS AND SPACES WITHOUT.

90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convector, Traps, Insulation, etc.

(H)

- Yes
- No

90a. Overall condition of piped heating and cooling distribution systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2022

90c. Expected Remaining Useful Life (Years):

20

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

HVAC Systems

Page Last Modified: 02/28/2023

91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

- Yes
- No

91a. Overall condition of ducted heating and cooling distribution systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2022

91c. Expected Remaining Useful Life (Years):

20

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

- Yes
- No

92a. Type of control system

- Pneumatic
- Electric
- Digital Direct Control (DDC)
- Web based DDC

92b. Overall condition of control systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

92c. Year of Last Major Reconstruction/Replacement:

2022

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

HVAC Systems

Page Last Modified: 02/28/2023

92d. Expected Remaining Useful Life (Years):

15

92e. Cost to Reconstruct/Replace \$:

(No Response)

92f. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Plumbing Systems

Page Last Modified: 02/28/2023

PLUMBING

93. Water Supply System (H)

- Yes
- No

93a. Types of pipes (check all that apply):

- Asbestos/transite
- Copper
- Galvanized
- Iron
- Lead
- PVC/CPVC/PEX/Plastic
- Other (specify)

93b. If "Other" please specify here

(No Response)

93c. Overall condition of water supply system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

93d. Year of Last Major Reconstruction/Replacement:

2022

93e. Expected Remaining Useful Life (Years):

30

93f. Cost to Reconstruct/Replace \$:

(No Response)

93g. Comments:

(No Response)

94. Sanitary System (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Plumbing Systems

Page Last Modified: 02/28/2023

94a. Types of pipes (check all that apply):

- Iron
- Galvanized
- Copper
- Glass/ceramic
- PVC/CPVC/ABS/poly propylene/plastic
- Lead
- Other (specify)

94a1. If "Other" please specify

(No Response)

94b. Types of special sanitary systems (Check all that apply)

- Acid waste and vent
- Grease interceptor
- Oil separator
- Pumping station
- Sediment trap
- Septic tank
- Waste water treatment plant

94c. Overall condition of sanitary system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

2022

94e. Expected Remaining Useful Life (Years):

5

94f. Cost to Reconstruct/Replace \$:

27,500.00

94g. Comments:

REPLACE SUMP PUMP SYSTEM IN BOILER ROOM

95. Storm Water Drainage System (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Plumbing Systems

Page Last Modified: 02/28/2023

95a. Types of pipes (check all that apply)

- Iron
- Galvanized
- Copper
- Lead
- Plastic
- Other

95a1. If "Other" please specify

(No Response)

95b. Overall condition of storm water drainage system

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

95c. Year of Last Major Reconstruction/Replacement

2022

95d. Expected Remaining Useful Life (Years)

20

95e. Cost to Reconstruct/Replace \$:

(No Response)

95f. Comments:

(No Response)

96. Hot Water Heaters (H)

- Yes
- No

96a. Type of fuel (check all that apply):

- Oil
- Natural Gas
- Electricity
- Propane
- Other (specify)

96b. If "Other" please specify

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Plumbing Systems

Page Last Modified: 02/28/2023

96c. Overall condition of hot water heaters:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

96d. Year of Last Major Reconstruction/Replacement:

2022

96e. Expected Remaining Useful Life (Years):

10

96f. Cost to Reconstruct/Replace \$:

(No Response)

96g. Comments:

REPORTED THAT CAPACITY OF SYSTEM IS UNDERSIZED. SYSTEM SIZE SHOULD BE EVALUATED.

97. Plumbing Fixtures (H)

- Yes
- No

97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

97b. Year of Last Major Reconstruction/Replacement:

2022

97c. Expected Remaining Useful Life (Years):

20

97d. Cost to Reconstruct/Replace \$:

(No Response)

97e. Comments:

(No Response)

98. Water Outlets/Taps for Drinking/Cooking Purposes (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Plumbing Systems

Page Last Modified: 02/28/2023

98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep, ice machines, etc).

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

98b. Year of last major reconstruction/replacement:

2022

98c. Expected remaining useful life (years):

20

98d. Cost to reconstruct/replace \$:

(No Response)

98e. Comments

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Fire Suppression Systems

Page Last Modified: 02/28/2023

Fire Suppression Systems

99. Fire Suppression System (H)

- Yes
- No

99a. Type of fire suppression system (check all that apply)

- Wet sprinkler system
- Dry sprinkler system
- Standpipes
- Hose cabinets
- Kitchen hood fire suppression
- Data special agent suppression
- Limited area sprinkler system
- Dust collector spark arrestor
- Paint booth fire suppression
- Other (describe)

99b. If "other" please describe below

(No Response)

99c. Overall condition of sprinkler systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

99d. Year of Last Major Reconstruction/Replacement:

2002

99e. Expected Remaining Useful Life (Years):

10

99f. Cost to Reconstruct/Replace \$:

(No Response)

99g. Comments:

SPRINKLER SYSTEM SERVES AUDITORIUM STAGE

100. Kitchen Hoods (H)

- Yes
- No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Fire Suppression Systems

Page Last Modified: 02/28/2023

100a. Type of hood

- Yes- Type 1 grease and smoke
- Yes- Type 2 heat and condensation

100b. Is kitchen exhaust system appropriate for all current appliances it serves?

- Yes
- No

100c. Overall Condition of Kitchen Hoods

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

100d. Year of Last Major Reconstruction/Replacement:

2002

100e. Expected Remaining Useful Life (Years):

10

100f. Cost to Reconstruct/Replace \$:

(No Response)

100g. Comments

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Electrical Systems

Page Last Modified: 02/28/2023

ELECTRICAL SYSTEMS

101. Electrical Power Distribution System (H)

- Yes
- No

101a. Electrical supply meets current needs:

- Yes
- No

101b. Condition of electrical power distribution system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

101c. Year of last major reconstruction/replacement?

2002

101d. Expected remaining useful life (years):

2

101e. Cost to reconstruct/replace:

500,000.00

101f. Comments:

Replace outdated electrical panels. Working spaces are not clean and clear surrounded panelboards and switches

102. Lighting Fixtures (H)

- Yes
- No

102a. Condition of lighting figures:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure

102b. Year of last major reconstruction/replacement:

2019

102c. Expected remaining useful life (years):

10

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Electrical Systems

Page Last Modified: 02/28/2023

102d. Cost to reconstruct/replace:

400,000

102e. Comments

Upgrade lighting and lighting controls in older section.

103. Emergency/ Exit Lighting Systems (H):

Yes

No

103a. Overall condition of emergency/exit lighting systems:

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical failure

103b. Year of last manjor reconstruction/replacement:

2022

103c. Expected remaining useful life (years):

10

103d. Cost to reconstruct/replace:

30000

103e. Comments

Replace incandescent wall pack fixtures

104. Emergency or standby power system (H)

Yes

No

105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)

Yes

No

105a. Overall condition of fire alarm system:

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical failure

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Electrical Systems

Page Last Modified: 02/28/2023

105b. Year of last major reconstruction/replacement:

2022

105c. Expected remaining useful life (years):

15

105d. Cost to reconstruct/replace:

(No Response)

105e. Comments

(No Response)

106. Carbon Monoxide Alarm System (H)

Yes

No

106a. Type of alarm system:

- 10-year battery stand alone alarm
- hardwired/interconnected detection and alarm
- gas detection (eg NG/CO)
- Other (specify)

106b. If "Other" please specify

(No Response)

106c. Overall condition of carbon monoxide alarm system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure

106d. Year of last major reconstruction/replacement:

2019

106e. Expected remaining useful life (years):

20

106f. Cost to reconstruct/replace:

(No Response)

106g. Comments

(No Response)

107. Communication Systems (H)

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Electrical Systems

Page Last Modified: 02/28/2023

107a. Type of communication system (check all that apply)

- Public Address
- Phones (VOIP)
- Phones (Cellular)
- Phones (other)
- Mass Notification
- Emergency voice communication fire alarm system
- Lockdown notification system
- Other (eg. radio) (describe below)

107b. If "Other" please describe

(No Response)

107c. Communication systems are adequate:

- Yes
- No

107d. Condition of communication system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure

107e. Year of last major reconstruction/replacement:

2010

107f. Expected remaining useful life:

10

107g. Cost to replace/reconstruct:

(No Response)

107h. Comments

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Student Transportation Facilities

Page Last Modified: 02/17/2023

Student Transportation Facilities

108. Is this building a transportation facility

Yes

No

109. Does this facility have a fuel dispensing system?

Yes

No

110. Does this facility have vehicle lifts

Yes

No

111. Does this facility have a bus wash system?

Yes

No

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Accessibility

Page Last Modified: 02/17/2023

ACCESSIBILITY

112. Exterior Accessible Route to Building (H)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- Yes
- No

112a. Features provided for exterior accessible route (check all that apply)

- Curb ramps
- Exterior ramps
- Handicap parking

112b. Cost of improvements needed to provide exterior accessible route to building \$:

(No Response)

112c. Comment

(No Response)

113. Is there an exterior accessible route to recreational facilities?

- Yes
- No

113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:

(No Response)

113b. Comments

(No Response)

114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that apply)

- Playground and play equipment
- Playfield(s)
- Athletic Field(s)
- Exterior Bleachers
- Bathroom Facilities
- Concession Stand

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Accessibility

Page Last Modified: 02/17/2023

114b. Comments

(No Response)

115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

Yes

No

115a. Cost of improvements needed to provide interior accessible route(s) as specified above \$:

(No Response)

115b. Comments

(No Response)

116. Does this facility have interior spaces that meet accessibility standards (check all that apply)

- Classrooms
- Labs (science, art, technology, etc)
- Shops
- Main Office
- Health Office
- Gymnasium
- Cafeteria
- Auditorium
- Stage
- Restrooms on each floor

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

116b. Comments

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Environment/Comfort/Health

Page Last Modified: 02/17/2023

ENVIRONMENT/COMFORT/HEALTH

117. General Appearance

117a. Overall Rating:

- Good
- Fair
- Poor

117b. Comments:

(No Response)

118. Cleanliness (H)

118a. Overall Rating:

- Good
- Fair
- Poor

118b. Comments:

(No Response)

119. Are there walk off mats; grills in the entryway?

- Yes
- No

119a. If yes: at least 6 feet long?

- Yes
- No

120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)

- Yes
- No

121. Lighting Quality (H):

121a. Types of lighting in general purpose classrooms (check all that apply):

- Daylight (natural)
- Not full spectrum
- Full spectrum
- LED
- Flourescent
- Other (describe)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Environment/Comfort/Health

Page Last Modified: 02/17/2023

121b. Are there blinds in the classroom to prevent glare?

- Yes
- No

121c. Overall Rating:

- Good
- Fair
- Poor

121d. Comments:

(No Response)

122. Evidence of Vermin (H)

122a. Is there evidence of active infestations of...(check all that apply)?

- Rodents
- Wood-boring or Wood-eating Insects
- Cockroaches
- Other Vermin
- None

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Indoor Air Quality

Page Last Modified: 02/26/2023

Indoor Air Quality

123. Mold (H)

123a. Is there visible mold or moldy odors?

- Yes
- No

123b. Are any surfaces constructed of any of the following materials?

- Paper-faced or gypsum products
- Cellulose products (typically ceiling tiles)
- Not Applicable

123c. Is there evidence of water intrusion?

- Yes
- No

123d. Estimated cost of necessary improvements \$:

(No Response)

123e. Comments:

(No Response)

124. Humidity/Moisture (H)

124a. Overall rating of humidity/moisture condition in building:

- Good
- Fair
- Poor

124b. Are any of the following found in/or around classroom areas (check all that apply)?

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

124c. Are any of the following found in/or around other areas (check all that apply)?

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Indoor Air Quality

Page Last Modified: 02/26/2023

125. Ventilation: fresh air intake locations, air filters, etc. (H)

125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?

- Yes
- No

125b. Is there accumulated dirt, dust or debris around fresh air intakes?

- Yes
- No

125c. Are fresh air intakes free of blockage?

- Yes
- No

125d. Is accumulated dirt, dust or debris in ductwork?

- Yes
- No

125e. Are dampers functioning as designed?

- Yes
- No

125f. Condition of air filters:

- Good
- Fair
- Poor

125g. Outside air is adequate for occupant load:

- Yes
- No

125h. Rating of ventilation/indoor air quality:

- Good
- Fair
- Poor

125i. Comments:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Indoor Air Quality

Page Last Modified: 02/26/2023

126. Indoor Air Quality (IAQ) Plan (H)

126a. Does the school district use EPA's *Tools for Schools* program?

- Yes
- No

126b. If No, is some other IAQ management plan used?

- Yes
- No

126c. Has the District assigned IAQ responsibilities to a designated individual?

- Yes
- No

126c.1 If Yes, what is their job title?

Sr. Custodian

127. Does the school practice Integrated Pest Management (IPM)? (H)

- Yes
- No

127a. Is vegetation kept one foot away from the building?

- Yes
- No

127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?

- Yes
- No

127c. Is there a certified pesticide applicator on staff?

- Yes
- No

127d. Are pesticides used in the building?

- Yes
- No

127d.1 If Yes, how are they typically applied?

- Spot treatment
- Area wide treatments

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Indoor Air Quality

Page Last Modified: 02/26/2023

127e. Are pesticides used on the grounds?

- Yes
- No

127e.1 If Yes, was an emergency exemption granted by the Board of Education?

- Yes
- No

128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?

(H)

- Yes
- No

128a. Has the facility been tested for the presence of radon?

- Yes
- No

128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- Yes
- No

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

- Yes, active mitigation system installed
- Yes, passive mitigation system made active
- Yes, ventilation controls (HVAC) adjusted
- Yes, other (describe)
- No action taken

128c.1 Describe other actions taken to mitigate elevated radon levels:

(No Response)

2022 BUILDING CONDITION SURVEY - 2022 - 0-002-MSHS

Emergency Shelter

Page Last Modified: 02/17/2023

Emergency Shelter

129. Does this building serve as an emergency shelter?

Yes

No